


Wiring diagram R 43 / R 53-1100

230-240V / 50 Hz

up to machine no. 8239



R 43 -900
Wiring diagram

up to machine no. 8239

Pos.	Description		Reference
CA	Capacitor 156 μ F		782.307
CB	Capacitor 25 μ F		P...385J
LS	Protection de puissance	up to machine no. 8239	P...352
M	Motor		785.200
R	Relais 2CR105-262	up to machine no. 8239	6630434
R.	Relais 2CR105-196		6630440
S	Tumbler switch for motor		6650454