

cleanfix[®]

SWISS MADE QUALITY

Ready for the Champions League!



Get a playmaker for your sports hall.

The robot RA660 Navi cleans your sports hall twice a day:
hygienically clean - extremely reliable - inexpensive
Everything about the new team player at www.ra660navi.com

Keeping sports halls hygienically clean is a must - a duty in Corona times!

It is recommended to clean halls twice a day. This task, and therefore responsibility towards the users, can be easily accomplished with the robot RA660 Navi - at a reasonable price! The qualified caretaker staff has more time to meet the other massively increased hygiene requirements.

For example, you program your robot RA660 Navi over lunchtime for the first cleaning, **an area of 1481.99 m² is cleaned in 1:10 h**, and for the second cleaning at night at 00:30 h.

Quality Control

Thanks to the Cleanfix reporting you have full control over the cleaning activity!

Status	Robot	Start Time	Stop Time	Location	Zone	Cleaned surface (m ²)	Info	PDF
🚫	Robo2	29.05.2020 12:16:08	not finished	Sports hall 2	Zone 2	0	In transit	Download
🚫	Robo1	29.05.2020 12:14:16	not finished	Sports hall 1	Zone 10	0	In transit	Download
✅	Robo1	29.05.2020 00:28:45	29.05.2020 01:39:06	Sports hall 1	Zone 10	1481.99	Cleaning done	Download
✅	Robo2	29.05.2020 00:15:36	29.05.2020 01:08:56	Sports hall 2	Zone 2	966.71	Cleaning done	Download
✅	Robo1	28.08.2020 12:09:16	28.08.2020 13:22:11	Sports hall 1	Zone 10	1482.88	Cleaning done	Download
✅	Robo2	28.08.2020 12:18:44	28.08.2020 13:12:38	Sports hall 2	Zone 2	965.31	Cleaning done	Download
✅	Robo1	28.05.2020 00:27:39	28.05.2020 01:38:42	Sports hall 1	Zone 10	1482.63	Cleaning done	Download
✅	Robo2	28.05.2020 00:16:27	28.05.2020 01:10:33	Sports hall 2	Zone 2	967.03	Cleaning done	Download

Cleaning Report

Sports hall 1 Cleaning status: ●

Cleaned area Cleaned surface: 1481.99 m² Zone 10

Cleaning Details

Status	Cleaning done	Status Meaning	Cleaning done
Battery Level	47%	Start Time	29.05.2020 00:28:45
Robot Name	Robo1	Stop Time	29.05.2020 01:39:06
Robot ID	00:40:42:03:4A:BC	Time Zone	(UTC+01:00) Amsterdam, Berlin, Bern, Rome, Stockholm, Vienna
Running Time	01:10:21		
Zone	Zone 10		

Technical data:			
Working width	66 cm	Cleaning speed	0.6 m/s
Working width suction cup	87 cm	Contents fresh / waste water tank	45 l
Running time max.	up to 3 h	Weight including batteries	260 kg
Battery capacity	AGM / Lithium	Dimensions (l/w/h)	925x850x880 mm

Ultra clean, ultra hygienic, absolutely cost-effective



Switzerland

Cleanfix Reinigungssysteme AG
 Stettenstrasse 15 | 9247 Henau-Uzwil/SG
 Tel. +41 71 955 47 47 | Fax +41 71 955 47 60
 info@cleanfix.com

Quality Control

Thanks to the Cleanfix reporting you have full control over the cleaning activity!

Status	Robot	Start Time	Stop Time	Location	Zone	Cleaned surface (m ²)	Info	PDF
🚫	Robo2	29.05.2020 12:16:08	not finished	Sports hall 2	Zone 2	0	In transit	Download
🚫	Robo1	29.05.2020 12:14:16	not finished	Sports hall 1	Zone 10	0	In transit	Download
✅	Robo1	29.05.2020 00:28:45	29.05.2020 01:39:06	Sports hall 1	Zone 10	1481.99	Cleaning done	Download
✅	Robo2	29.05.2020 00:15:36	29.05.2020 01:08:56	Sports hall 2	Zone 2	966.71	Cleaning done	Download
✅	Robo1	28.08.2020 12:09:16	28.08.2020 13:22:11	Sports hall 1	Zone 10	1482.88	Cleaning done	Download
✅	Robo2	28.08.2020 12:18:44	28.08.2020 13:12:38	Sports hall 2	Zone 2	965.31	Cleaning done	Download
✅	Robo1	28.05.2020 00:27:39	28.05.2020 01:38:42	Sports hall 1	Zone 10	1482.63	Cleaning done	Download
✅	Robo2	28.05.2020 00:16:27	28.05.2020 01:10:33	Sports hall 2	Zone 2	967.03	Cleaning done	Download


This overview shows an example with 2 robots and two sports halls.

With the [Download](#) you receive the detailed Cleaning Report

Cleaning Report

Sports hall 1 Cleaning status: ✅

Cleaned area Cleaned surface: 1481.99 m² Zone 10



Cleaning Details

Status	Cleaning done	Status Meaning	Cleaning done
Battery Level	47%	Start Time	29.05.2020 00:28:45
Robot Name	Robo1	Stop Time	29.05.2020 01:39:06
Robot ID	00:40:42:03:4A:BC	Time Zone	(UTC+01:00) Amsterdam, Berlin, Bern, Rome, Stockholm, Vienna
Running Time	01:10:21		
Zone	Zone 10		

This cleaning report shows a sports hall with 1481.99 m² cleaned in one hour and ten minutes (1:10:21).

The cleaning paths (marked red) of the robot are clearly visible. You have full control that the entire hall is cleaned. No source of error from unnecessarily double cleaned areas or from forgotten areas.

The cleaning details show among other things the battery level, the exact running time and the exact cleaning time.